


Work Order ID 117294

June-05-14 11:41:15 AM

117294

Page 1

Item ID: D2500-1-190 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Ext'n - 'I' Beam Tube 4"
 Start Date: 6/05/14 Start Qty: 4.00 ***4*** Cust Item ID:
 Required Date: 6/05/14 Req'd Qty: 4.00 ***4*** Customer:
 Reference: scrap- dented

Approvals: Process Plan:  Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2500	Rev H								

105 0.00

105

Skid tubes

Skid tubes

Memo

PULL FROM STK:
4 X D2500-1-190 B105279

SCRAP/DESTROY, PARTS ARE DENTED

0.00

14-06-12 PLM DP

140

QC21- Final Inspection - Work Order Release

0.00

140


QC

Memo

Quality Control

0.00

MLJ 14-06-12

 14-06-12

Picklist Print

June-05-14 11:41:14 AM

Page 1

Work Order ID: 117294

117294

Parent Item: D2500-1-190

D2500-1-190

Parent Item Name: Ext'n -1' Beam Tube 4"

Start Date: 6/05/14

Required Date: 6/05/14

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP: G 02.09.05 Added DSK 066 KJ/RF
 IPP: H 07.07.06 rev G dwg EC IPP Rev:I as per
 dwg revH DD 10.02.23 verified byEC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D2500-1-190

Manufactured

No

Each

75.0000

4

D2500-1-190

Ext'n -1' Beam Tube 4"

Location

Loc Qty

Loc Code

HALL

87

105279

6

LG

-12

117806

69